

SAFETY PRECAUTIONS



- Tightening and loosening of bolts must be in accordance with instructions given in the leaflet “Installation Procedures” and where local regulations permit!
- Wear safety glasses!
- Wear hard hat!
- Use safety footwear!
- Use K VX recommended grease only!
- Always use a good tight spanner!
- Do not stand directly in front of the bolts during torque-up!
- Stand well clear of the spanner stand (minimum 3 meters) when force is applied!*)
- Always make sure the stand foot is on firm and level ground!*)
- Keep constant contact with driver during torque-up procedure!*)
- Always use correct hand signals to communicate with driver!*)

**) Where local regulations permit*

503110 11/2010